

SCSVMV

DEPARTMENT OF CIVIL AND STRUCTURAL ENGINEERING

SITE VISIT- NURSING COLLEGE CONSTRUCTION WORK

On February 5, 2024, at 10:00 a.m., staff members from Civil and SE went to see the ongoing building work for the nursing college in Enathur, Kanchipuram. The report with photos is given below.

By 10.10 a.m., twelve staff members from the Civil and Structural Engineering Department had arrived at the location. The site supervisor gave instructions on safety precautions, and all staff were given helmets to wear before entering the structure that was still under construction.

The college building, hostel building, canteen, and staff quarters were visited by the staff, who cleared their doubts with the supervisors. The plan of the building gone through by the faculties. They asked to bring the students after 20 days by considering the safety.

A high tea was provided by them, and reached the university by 11.45 a.m.

S.No	Name of the Faculty	Signature of the Faculty
1.	Dr. R.Sumathi	Assistant Professor-II/ HOD i/c
2.	Dr.G.Kesavan	Assistant Professor-III
3.	Mr.K.Vasu	Assistant Professor-III
4.	Dr. M.SureshKumar	Assistant Professor-II
5.	Mr.V.John Sundarraj	Assistant Professor-II
6.	Mr. M.Dinesh	Assistant Professor-II
7.	Mr.M.Vimalanathan	Assistant Professor-I
8.	Mr. R.Raveendiran	Sr. Lab Instructor
9.	Mr.D.Elangovan	Lab Instructor
10.	Mr.J.Jaisankar	Lab Instructor
11.	Mr.S.Madhanagopal	Lab Instructor
12.	Mr.D.Thavamani	Lab Instructor

Photos Taken During Visit



Plan Shown by the Site Supervisor



Class Rooms with Gallery Arrangement



Nursing College building



College Building-Front view




Staff Quarters



Discussion about Plan

Hostel Building



Discussion with Architect

